HAWAI;

LINDA LINGLE



CHIYOME L. FUKINO, M.D.

STATE OF HAWAII
DEPARTMENT OF HEALTH
SAFE DRINKING WATER BRANCH

FE DRINKING WATER BRANCH
919 Ala Moana Boulevard, Room 308
Honolulu, Hawaii 96814

January 11, 2010

Mr. Lono Tyson
Director
Department of Environmental Management
25 Aupuni Street
Hilo, Hawai'i 96720

ATTENTION: Mr. Gene Quiamas

Dear Mr. Tyson:

SUBJECT: KOMOHANA HEIGHTS;

UNDERGROUND INJECTION CONTROL (UIC) PROGRAM'S REVIEW OF

INJECTION-WELL CESSPOOL BACKFILLING

FINAL COMPLETION REPORT DATED 12/18/2009,

UIC FILE NO. UH-2597

Based on the submitted information, the abandonment work for the two injection wells appears completed. Therefore, as of this letter's date, UIC File UH-2597 is closed.

Please be aware that this file closure does not absolve the facility from responsibility should environmental problems arise from the past construction or operation of the injection wells.

If you have any questions regarding this subject, please contact Jaime Rimando of the Safe Drinking Water Branch at 586-4258 (Honolulu) or call direct toll free from Big Island at 974-4000, ext. 64258.


Sincerely,


STUART YAMADA, P.E., CHIEF Safe Drinking Water Branch

Environmental Management Division

JR:nbp

c: Katherine Rao
Ground Water Office (WTR-9)
U.S. Environmental Protection Agency
75 Hawthorne Street
San Francisco, Ca 94105





December 17, 2009

Komohana Heights Large Capacity Cesspool Replacement Hilo, Hawai'i, County of Hawai'i Department of Environmental Management, Wastewater Division Job No. WW-3719

Subject:

Cesspool Closure Report – State of Hawai'i Department of Health Safe Drinking Water Branch (SDWB), UIC Permit #UH-2597

Method of Closure: Cesspool A

December 15, 2009

Cesspool Diameter: ±13' Depth: ±22'6"

- 1. The cesspool cover was located and a three foot (3') wide section of the cesspool cover was removed to expose the cesspool.
- 2. Inverts were verified and the existing 8" VCP pipe was connected to the new sewer manhole #8 to bypass the cesspool.
- 3. B&B Pumping Service was on site to clean, pump and removed the liquids and solids from the cesspool's walls and bottom. Approx. 4' of liquids and solids (3,200 gals.) were disposed at the Hilo Wastewater Treatment Plant.
- 4. Upon completion of the cleaning and pumping, visual inspection was done. No ground water was evident.

December 16, 2009

1. 100 cubic yards of Controlled Low-Strength Material (CLSM) 500 psi was used to fill the cesspool. The material was not permitted to fall greater than 6'. To achieve this, the contractor inserted an 18" corrugated pipe into the hole and released the concrete into the corrugated pipe.

Method of Closure: Cesspool B

December 16, 2009


Cesspool Diameter: 13' Depth: 23'

- 1. The cesspool cover was located and a three foot (3') trench was wide section of the cesspool cover was removed to expose the cesspool.
- 2. Inverts were verified and the existing 8" VCP pipe was connected to the new sewer manhole #10 to bypass the cesspool.
- 3. B&B Pumping Service was on site to pump the liquids and some solids from the bottom of the cesspool. The Hilo Line Maintenance Section also assisted to remove heavy debris (rags) from the walls and bottom of the cesspool using a Vactor Truck. Approx. 2' of liquids and solids (1,500 gals.) were disposed at the Hilo Wastewater Treatment Plant.
- 4. Upon completion of the cleaning and pumping, visual inspection was done. No ground water was evident.


December 17, 2009

1. 100 cu. yards of Controlled Low-Strength Material (CLSM) 500 psi was used to fill the cesspool. The material was not permitted to fall greater than 6'. To achieve this, the contractor inserted an 18" corrugated pipe into the hole and released the concrete into the corrugated pipe.


Cesspool A – Komohana Heights LCC Closure – Permit # UH 2597




Cesspool A Prior to cleaning




Cesspool A - Prior to Cleaning




Cesspool A - Cleaning of Side Walls




Cesspool A - Side wall view




B&B Pumping




Cesspool A - Pumping of Sludge & Debris




Cesspool A - early stage of backfilling




Cesspool A – Method of backfilling Trunk




Cesspool A - Trunk





Cesspool A – backfilling in lifts w/CLSM




Hawai'i County is an equal opportunity provider and employer.


Cesspool B – Komohana Heights LCC Closure – Permit # UH 2597




Cesspool B- Cutting of Cover




Cesspool B - prior to cleaning




Cesspool B after cleaning




Cleaning of Cesspool - B&B




Cesspool B - gradual lifts







Cesspool B − ½ full




Cesspool B – ¾ full



Cesspool B - Filling to Cover



Cesspool B - Closure Complete



Cesspool B - Final View